

SC-P-APC

Optical Fiber Field Fast Assembly Connector

The optical fiber field fast assembly connector is used to connect 2x3mm flat drop cable to ONU/ONT easily and quickly. It also can be used in distribution box to lead a drop cable from splitter or adapters panel.

Fiber Type	ITU G657A, G657B, G652D
Fiber Cladding	125um
Fiber Coating	250um
Fiber Cable	2x3mm Flat Drop Cable
Reuse	5 times
APC Angle	8° ±0.3
Insertion Loss	≤0.5dBm
Typical Insertion Loss	0.3dBm
Tension	40N
Mechanical Durability	≤0.3dB
Tension Strength	≤0.3dB(20N)
Working Temperature	-40 to +85°C

Standard

Apperance	GR-326-4.2.3
Insertion Loss	GR-326-4.2.1
Return Loss	GR-326-4.2.1
Thermal Age	GR-326-4.4.2.1
Thermal Cicle	GR-326-4.4.2.2
Humidity Agent	GR-326-4.4.2.3
Impact	GR-326-4.4.3.3
Vibration	GR-326-4.4.3.1
Durability	GR-326-4.4.3.8

